

13 June 2024

中華電力有限公司  
CLP Power Hong Kong Limited

## **CLP Power Conducts Review on Management of Power System**

CLP Power Hong Kong Limited (CLP Power) is conducting a detailed investigation into the cause of the power incident in Wong Tai Sin last night (12 June) and will submit the investigation report to the Government. CLP Power apologises again for the inconvenience caused to customers who were affected by the incident.

CLP Power appreciates the concern of the Environment and Ecology Bureau (EEB) regarding recent power incidents, and the public expectation for a reliable power supply. Regarding the suggestion raised by EEB at the meeting today, CLP Power will set up a special working group with the Electrical and Mechanical Services Department to conduct a review on the management of the power system and submit a report within 12 months.

The power system is complex and closely intertwined. A robust asset management and maintenance system is instrumental to a reliable power supply. CLP Power has been managing our assets responsibly and is committed to keeping pace with the times and adopting practical measures to continuously improve the reliability of power supply.

CLP Power will strive to provide a reliable and safe power supply to the public, and will enhance communication with the community with a view to continuing our contribution to the sustainable development of Hong Kong.

- Ends -